



FIG. 2





## RF Pocket PC Handheld Data Collection Flow




FIG. 4

#### **Desktop Data Collection Flow**




FIG. 5

# **Desktop Data Reporting Flow**





FIG. 6

### Process to Add Users to the System



## Creating Inspection Points or Data Collection Tests Flow




FIG. 8

# Creating a Schedule Flow




FIG. 9

## Adding and Updating Part Information









FIG. 10












































FIG. 26









Plant Floor Data Collection System - Patent Pending
Plant.View

Workstation Type Information

Name

674

Is This Workstation Type Portable? Yes © No © 676


User Name


678


PIN


680


Cancel
FIG. 32
































FIG. 45

